


County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R. 3 E.

CHAINS

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap mkd.



from which

A pine, 72 ins. diam., bears N.53°E., 38 lks.

dist., mkd. $\frac{1}{4}$ S 32 B T

A hemlock, 8 ins. diam., bears S.73°W., 23 lks.

dist., mkd. $\frac{1}{4}$ S 31 B T

Desc. 80 ft. along broken NE. slope.


46.20 Rock, 56x8x18 ft. above ground, on line.

51.30 Draw, course E., asc. 168 ft. over broken SE. slope.

65.30 Spur, slopes E., desc. 108 ft. over N. slope.

70.60 Draw, course E., asc. 108 ft. over SE. slope.

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for the cor. of secs. 29, 30, 31, and 32, with brass cap mkd.



from which

A pine, 26 ins. diam., bears N.62°E., 50 lks.

dist., mkd. T 25 S R 3 E S 29 B T

A fir, 14 ins. diam., bears S.20°E., 96 lks.

dist., mkd. T 25 S R 3 E S 32 B T

A fir, 18 ins. diam., bears S.31°W., 116 lks.

dist., mkd. T 25 S R 3 E S 31 B T

A fir, 52 ins. diam., bears N.15°W., 271 lks.

dist., mkd. T 25 S R 3 E S 30 B T

Land; mountainous.

Soil; rocky, 4th rate.

Timber; fir, pine, hemlock, madrona, cedar, and yew.

Undergrowth; vinemaple, rhododendron, buckbrush,

manzanita, chinquapin, and huckleberry.