

## County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R. 3 E

CHAINS

A fir, 20 ins. diam., bears N.27°W., 68 lks.  
dist., mkd. T 25 S R 3 E S 18 B T

Land mountainous

Soil; rocky, 4th rate.

Timber; fir, pine, hemlock, cedar, and yew.

Undergrowth; chinquapin, vinemaple, hazel, manzanita,  
willow, alder, rhododendron, and huckleberry.

- S.89°54'E., on a random line bet. secs. 17 and 20
- 40.00 Set temp.  $\frac{1}{4}$  sec. cor.
- 80.24 Intersect N. and S. line, 21 lks. S. of the cor. of  
secs. 16, 17, 20, and 21
- Thence
- S.89°57'W., on true line bet. secs. 17 and 20
- Asc. 665 ft. over broken SE. slope, to the  $\frac{1}{4}$  sec. cor.,  
Through heavy timber and medium undergrowth.
- 14.00 Spring, course SE.,
- 35.90 Way trail, bears SE. and NW.,
- 40.12 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in  
the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.
- |               |      |
|---------------|------|
| $\frac{1}{4}$ | S17  |
| —             | S20  |
|               | 1931 |
- from which
- A fir, 7 ins. diam., bears N.13°E., 6 lks.  
dist., mkd.  $\frac{1}{4}$  S 17 B T
- A fir, 7 ins. diam., bears S.56°E., 17 lks.  
dist., mkd.  $\frac{1}{4}$  S 20 B T
- Along broken S. slope, through scattered timber and  
dense undergrowth.
- 51.20 Desc. 345 ft. over broken SW. slope, to cor.
- 60.80 Creek, 2 lks. wide, course S.75°W.,
- 62.40 Spur, slopes S.,
- 72.90 Small stream, course S.,
- 74.70 Spur, slopes S.,
- 80.24 Cor. of secs. 17, 18, 19, and 20.