

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R. 3 E.

CHAINS

- 79.90 The cor. of secs. 5, 6, 7, and 8
Land; mountainous
Soil; rocky, 4th rate.
Timber; fir, pine, hemlock, cedar, and yew.
Undergrowth; alder, vinemaple, huckleberry, buckbrush,
and rhododendron.
-
- 40.00 S.89°47'W., on a random line bet. secs. 6 and 7
Set temp. $\frac{1}{4}$ ' sec. cor.
- 73.49 Intersect the W. bdy. of Tp. 16 lks. N. of the cor.
of secs. 1, 6, 7, and 12, which is an iron post, 2 ins.
diam., 12 ins. above ground, firmly set, mkd.
and witnessed as described in the official record
Thence
N.89°40'E.; on true line bet. secs. 6 and 7
Asc. 697 ft. over broken NW. slope, through heavy
timber and medium undergrowth
- 33.49 A fir, 42 ins. diam., for the $\frac{1}{4}$ sec. cor., mkd.
 $\frac{1}{4}$ S 6 on N., and
S 7 on S., side

from which
A fir, 22 ins. diam., bears S.7°E., 118 lks.
dist., mkd. $\frac{1}{4}$ S 7 B T
A fir, 40 ins. diam., bears N.3°W., 130 lks.
dist., mkd. $\frac{1}{4}$ S 6 B T
Ridge spur, bears E. and S.80°W., asc. 246 ft. over
gradual W. slope, along top of ridge.
- 67.30 Ridge, bears NW. and SE., desc. 190 ft. over NE.
slope.
- 73.49 The cor. of secs. 5, 6, 7, and 8.
Land; mountainous.
Soil; mountain loam, 3rd rate.
Timber; fir, hemlock, pine, and cedar.
Undergrowth; vinemaple, wild currant, huckleberry,