

County Surveyor's Record, Douglas County, Oregon

East Boundary of Tp. 25 S., R 5 E.

CHAINS

T 25 S S 12 on SW and R 5 E S 1 on NW with 1 notch on N and 5 on S edges, from which;

A Fir, 6 ins. diam., bears S.44*W., 14 lks.

dist. marked T 25 S R 5 E S 12 B T.

A Fir, 12 ins. diam., bears N.75*W., 9 lks.

dist. marked T 25 S R 5 E S 1 B T.

No stone obtainable.

Land; mountainous.

Soil; Volcanic ashes 4th rate.

Timber; Hemlock, and Rhododendron.

Mountainous land heavily timbered or covered with dense undergrowth. 80.00 chains.

South on E bdy. of sec. 12, over mountainous land, heavily timbered and with dense undergrowth.

Ascending a steep NE slope from cor.

6.00 Summit of ascent bears NW and SE Descend steeply.

13.00 Leave heavy timber bears E and W enter scattering dead timber and dense undergrowth of ceanothus

40.00 Set A Fir post, 3 ft. long, 4 ins. sq., 2 ft in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S 12 on W and 8 on E faces, from which;

A Fir, 5 ins. diam., bears N.35*E., 9 lks.

dist. marked $\frac{1}{4}$ S 8 B T.

A Fir, 6 ins. diam., bears S.55*W., 9 lks.

dist. marked $\frac{1}{4}$ S 12 B T.

Land; mountainous.

Soil; volcanic ashes 4th rate.

Timber; Fir, Hemlock and Larch.

Undergrowth ceanothus, hemlock and Rhododendron.

Mountainous land heavily timbered or covered with dense undergrowth. 40.00 chains. Sept. 3rd, 1902.