

County Surveyor's Record, Douglas County, Oregon

South Boundary of T 24 S., R 5 1/2 E.

CHAINS

Land mountainous.  
 Soil, volcanic ashes, 4th rate.  
 Timber hemlock and pine.  
 Undergrowth hemlock and pine.  
 Mountainous land heavily timbered or covered with dense undergrowth and exceptionally difficult to survey.  
 80.00 chains. Sept. 17, 1902.

East Boundary of T 25 S R. 5 1/2 E.  
 Same Deputy and Contract.

I commence at the cor. of Tps. 24 and 25 S Rgs. 5 1/2 and 6 E. Which I previously establish and run South on Rg. line bet. secs. 1 and 6 over mountainous land, heavily timbered and covered with dense undergrowth and exceptionally difficult to survey.  
 Ascending N. slope of mountain.

20.00 Cliff 50 ft. high bears E. and W.

40.00 Set a hemlock post, 3 ft. long, 4 ins. sq. 2 ft. in ground, for 1/4 sec. cor. marked 1/4 S 1 on W. and 6 on E. face, from which,  
 A hemlock, 7 ins. in dia., bears N.82\*E. 8 lks. dist., marked 1/4 S 6 B T.  
 A hemlock, 12 ins. in dia., bears S.40\*W. 3 lks. dist., marked 1/4 S 1 B T.  
 No stone obtainable.

43.50 Creek 3 lks. wide, course NE.

56.00 Lake of about 2 acres, bears E. 40 lks. dist.

80.00 Set a hemlock post, 3 ft. long, 4 ins. sq. 2 ft. in ground, for cor. of secs. 1,12,6 and 7 marked T 25 S S 6 on NE. R 6 E S 7 on SE. S 12 on SW. and R 5 1/2 E S 1 on NW. face with 1 notch on N and 5 on S. edges from which,  
 A hemlock, 20 ins. in dia., bears N.35\*E. 21 lks. dist., marked T 25 S R 6 E S 6 B T.  
 A hemlock, 16 ins. in dia., bears S.75\*E. 50 lks. dist., marked T 25 S R 6 E S 7 B T.  
 A hemlock, 10 ins. in dia., bears S.35\*W. 37 lks. dist., marked T 25 S R 5 1/2 E S 12 B T.