

County Surveyor's Record, Douglas County, Oregon

Subdivisions of Tp. 25 $\frac{1}{2}$ S., R 2 E.

CHAINS

From the cor. of secs. 5, 6, 31, and 32, on S. bdy. of Tp., as described in the field notes of T. 26 S., R. 2 E.

N.0*04'W., bet. secs. 31 and 32

Along broken W. slope, through medium timber and dense undergrowth.

10.00 Desc. 171 ft. over NW. slope.

17.00 Spur, slopes NW., desc. 137 ft. over NE slope.

25.00 Draw, course NE.,

29.60 Small stream, course E., asc. 20 ft. along SE slope.

34.58 Intersect S. bdy. of T. 25 S., R 2 E., 22 lks. S.89*55'W.

of $\frac{1}{4}$ sec. cor. of sec. 31 only, hereinbefore described; at point of intersection set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for closing cor. of secs. 31 and 32, with brass cap marked

T25S R2E	
S31	

S31	S32
T25 $\frac{1}{2}$ S	R2E
C	C
1930	

from which;

A Hemlock, 30 ins. diam., bears S.60*E., 54 lks.

dist. marked T 25 $\frac{1}{2}$ S R 2 E S 32 C C B T

A Fir, 5 ins. diam., bears S.37*W., 31 lks.

dist. marked T 25 $\frac{1}{2}$ S R 2 E S 31 C C B T

Land; mountainous.

Soil; rocky, 4th rate.

Timber, Fir, Hemlock, Cedar, Pine, Yew, Madrona, and

Chinquapin,

Undergrowth; Rhododendron, VineMaple, Buck Brush,

Hazel, Huckleberry and Arrowwood.