

Subdivision of T. 25 1/2 S., R. 3 E.

CHAINS

I commence the subdivisional survey at the cor. of secs. 1, 2, 35 and 36. on the S. bdy. of the Tp., which is an iron post. 2 ins. diam., 9 ins. above ground, firmly set, marked and witnessed as described in the official record.

N. 68° 01' W., bet. secs. 35 and 36.

Asc. 52 ft. over broken SE. slope, through heavy timber and medium undergrowth.

7.50 Spur, slopes E., desc. 208 ft. over NE., changing to N. slope.

16.90 Small stream, course NE., asc. 30 ft. along broken E. slope, to cor.

26.10 Draw, drains E.,

35.88 Intersect S. bdy. of sec. 35, T. 25 S., R. 3 E., 5.24 chs. E. of the 1/4 sec. cor. of sec. 35 only
At point of intersection set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for closing cor. of secs. 35 and 36, with brass cap mkd.



from which:

A fir, 12 ins. diam., bears S. 68° E., 50 lks.
dist. mkd. T 25 1/2 S R 3 S 36 C C B T.

A fir, 16 ins. diam., bears S. 26° W., 51 lks.
dist. mkd. T 25 1/2 S R 3 E S 35 C C B T

Land: mountainous.

Soil: rocky, 4th rate.

Timber: fir, pine, cedar; hemlock and madrona.

Undergrowth: chinquapin, elderberry, serviceberry, and huckleberry.