

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the Willamette Meridian
through T. 26 S.

CHAINS

A hemlock, 10 ins. diam., bears S.45*E., 8 lks.

Marked T 26 S R 1 E S 30 B T.

A hemlock, 12 ins. diam., bears S.61*W., 20 lks.

Marked T 26 S R 1 W S 25 B T.

A yew, 6 ins. diam., bears N.71*W., 20 lks. dist.

Marked T 26 S R 1 W S 24 B T.

Land, mountainous.

Soil, loam and stony, 3rd rate.

Timber, fir, hemlock and yew.

Undergrowth, rhododendron, yew, hemlock and vine maple.

N.0*26*E., resurveying the E. bdy. of sec. 24.

Descend 214 ft. over broken NW. slope, through timber
and brush.

6.44 Point for the closing cor. of secs. 19 and 30, later
determined and hereinafter described.

12.20 Creek, 1 lk. wide, course NW.

22.30 Creek, 2 lks. wide, course N.75*W.

26.80 Bluff, 20 ft. high, bears E. and W., faces N.

29.40 Ravine, course NW.

Ascend 93 ft. over SW. slope.

39.83 Intersect the old $\frac{1}{4}$ sec. cor., established for secs. 19
and 24, which is basalt stone, 5x10x8 ins. above
ground with the old marks weathered off.

I change this cor. to refer to sec. 24 only, destroying
the marks on the SE. bearing object.

Alongside of old cor. stone,

Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in
the ground, for the $\frac{1}{4}$ sec. cor. of sec. 24 only, with
brass cap, marked

$\frac{1}{4}$ S24 |
1928

from which