

County Surveyor's Record, Douglas County, Oregon

Survey of the E. Bdy. of T. 26 S., R. 1 E.

CHAINS

- 63.50 Draw, course NE.
Ascend 272 ft. over broken S. slope.
- 74.20 Draw, course E.
- 78.10 Spur, slopes E.
- 80.00 Set an iron post, 3 ft. long, 2 ins. in diam., 27 ins. in ground, for the cor. of secs. 19, 24, 25 and 30, with brass cap marked,

T26S	
R1E	R2E
S24	S19

S25	S30
1928	

from which

A cedar, 24 ins. diam., bears N.71*E., 22 lks.

Marked T 26 S R 2 E S 19 B T.

A madrone, 4 ins. diam., bears S.35*E., 32 lks.

Marked T 26 S R 2 E S 30 B T.

A pine, 5 ins. diam., bears S.10*W., 32 lks. dist.

Marked T 26 S R 1 E S 25 B T.

A fir, 30 ins. diam., bears N.46*W., 23 lks. dist.

Marked T 26 S R 1 E S 24 B T.

Land, mountainous.

Soil, rocky and loam, third rate.

Timber, fir, madrone, pine and cedar.

Undergrowth, vine maple and chinquapin.

North, between secs. 19 and 24.

Descend 1103 ft. over broken NE. slope, through timber and brush.

- 31.50 Creek, 3 lks. wide, course NE.

Ascend 318 ft. over SE. slope.

- 40.00 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in ground, for the $\frac{1}{4}$ sec. cor., with brass cap marked.