


Survey of the E. Bdy. of T. 26 S., R. 1 E.

CHAINS

Land, mountainous.
 Soil, rocky loam, third rate.
 Timber, fir and hemlock.
 Undergrowth, vine maple and chinquapin.

North, bet. secs. 13 and 18.
 Ascend 516 ft. over broken S. slope, through timber and brush.

- 7.40 Draw, course SE.
- 18.50 Spur, slopes E.
- Descend 88 ft. over NE. slope.
- 25.70 Creek, 2 lks. wide, course E.
 Ascend 414 ft. over SE. slope.
- 40.00 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in ground, for the $\frac{1}{4}$ sec. cor., with brass cap marked,



from which

A fir, 8 ins. diam., bears N.45*E., 15 lks. dist.

Marked $\frac{1}{4}$ S 18 B T.

A fir, 10 ins. diam., bears S.78*W., 80 lks. dist.

Marked $\frac{1}{4}$ S 13 B T.

A lone dead snag, on top of a prominent rock, bears

N.14 $\frac{1}{2}$ *E.

Ascend 606 ft. over broken SE. slope.

- 59.50 Draw, course SE.
- 75.60 Spur, slopes E.
 Descend 25 ft. over N. slope.
- 80.00 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for the cor. of secs. 7, 12, 13, and 18, with brass cap marked,