

County Surveyor's Record, Douglas County, Oregon

Survey of the E. Bdy. of T. 26 S., R. 1 E.

CHADSO

- 40.00 Set an iron post, 3 ft. long, 1 ins. in diam., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap marked,

$$\begin{array}{c} \frac{1}{4} \\ | \\ S\ 1\ | \ S\ 6 \\ | \\ 1928 \end{array}$$

from which

A hemlock, 16 ins. diam., bears N.46*E., 37 lks.

Marked $\frac{1}{4}$ S 6 B T.

A hemlock, 18 ins. diam., bears N.28*W., 47 lks.

Marked $\frac{1}{4}$ S 1 B T.

Descend 1012 ft. over broken NE. slope.

- 47.00 Spur, slopes NE.

- 69.20 Dry Creek bed, 3 lks. wide, course NE.

- 80.00 Set an iron post, 3 ft. long, 3 ins. in diam., 27 ins. in the ground, for the cor. of Tps. 25 $\frac{1}{2}$ and 26 S., Rs. 1 and 2 E., with brass cap marked,

$$\begin{array}{c} T25\frac{1}{2}S \\ R1E\ | \ R2E \\ S36\ | \ S31 \\ \hline S\ 1\ | \ S\ 6 \\ T26S \\ 1928 \end{array}$$

from which

A fir, 8 ins. diam., bears N.43*E., 27 lks. dist.

Marked T 25 $\frac{1}{2}$ S R 2 E S 31 B T.

A fir, 9 ins. diam., bears S.45*E., 16 lks. dist.

Marked T 26 S R 2 E S 6 B T.

A fir, 9 ins. diam., bears S.23*W., 18 lks. dist.

Marked T 26 S R 1 E S 1 B T.

A hemlock, 5 ins. diam., bears N.81*W., 29 lks.

Marked T 25 $\frac{1}{2}$ S R 1 E S 36 B T.

Land, mountainous.

Soil, rocky and loam, third rate.

Timber, fir, hemlock and madrone.

Undergrowth, vine maple and rhododendron.