

Subdivisions, T. 26 S., R. 1 E.

CHAINS

- 9.50 Draw, course NE.  
Ascend 84 ft. over broken E. slope.
- 17.20 Spur, slopes N.  
Descend 800 ft. over broken NW. slope.
- 30.40 Enter draw, course W., from the SE.
- 34.70 Leave draw, course SW., from the E.
- 39.61 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in the ground, for the witness  $\frac{1}{4}$  sec. cor., with brass cap marked,
- S26  
WC  $\frac{1}{4}$  ———  
S35  
1928
- from which
- A hemlock, 10 ins. diam., bears S.54\*E., 48 lks.  
Marked W C  $\frac{1}{4}$  S 35 B T.
- A cedar, 18 ins. diam., bears N.5\*W., 29 lks. dist.  
Marked W C  $\frac{1}{4}$  S 26 B T.
- 40.16 True point for the  $\frac{1}{4}$  sec. cor. falls on slide rock on steep W. slope, where it is impracticable to establish a permanent corner.
- 40.30 Limpy Creek, 10 lks. wide, course NE.  
Ascend 510 ft. over broken SE. slope.
- 50.10 Top of rock bluff, 15 ft. high, bears N. and S. faces E.
- 55.80 Spur, slopes S.20\*E.  
Descend 63 ft. over SW. slope.
- 58.70 Small draw, course S.
- 63.00 Small draw, course SE.  
Ascend 430 ft. over SE. slope.
- 75.30 Ridge, bears N. and S.  
Descend 224 ft. over W. slope.
- 80.32 The cor. of secs. 26, 27, 34 and 35.  
Land, mountainous.  
Soil, rocky loam, third rate.  
Timber, fir, cedar and hemlock.  
Undergrowth, vine maple and second growth timber.