

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 26 S.; R. 1 E.

CHAINS

N.0*02'W., on a random line bet. secs. 2 and 3.

40.00 Set temp. $\frac{1}{4}$ sec. cor.80.39 Intersect the N. bdy. of the Tp., 9 lks. E. of the cor.
of secs. 2, 3, 34 and 35, hereinbefore described.

Thence,

S.0*06'E., on a true line bet. secs. 2 and 3.

Over mountainous land, through timber and brush.

Descend 820 ft. over broken S. slope.

23.90 Spring branch, 1 lk. wide, course W.

35.20 Spring branch, 1 lk. wide, course W.

40.39 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in
the ground, for the $\frac{1}{4}$ sec. cor., with brass cap marked,
$$\begin{array}{c} \frac{1}{4} \\ | \\ S\ 3\ | \ S\ 2 \\ | \\ 1928 \end{array}$$

from which

A fir, 8 ins. diam., bears S.77*E., 44 lks. dist.

Marked $\frac{1}{4}$ S 2 B T.

A fir, 16 ins. diam., bears S.57*W., 46 lks. dist.

Marked $\frac{1}{4}$ S 3 B T.

40.55 Creek, 2 lks. wide, course S.15*E.

Descend 550 ft. over broken S. slope.

73.70 Jackass Creek, 4 lks. wide, course S.20*W.

80.39 The cor. of secs. 2, 3, 10 and 11.

Land, mountainous.

Soil, rocky loam, third rate.

Timber, fir, pine and cedar.

Undergrowth, vine maple and service berry.

From the cor. of secs. 3, 4, 33 and 34 on the S. bdy. of
the Tp., as described in the notes of T. 27 S., R. 1 E.

Thence,