

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 26 S., R. 1 E.

CHAINS

40.00 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap marked,



from which

A fir, 18 ins. diam., bears N.68*E., 14 lks. dist.

Marked $\frac{1}{4}$ S 21 B T.

A fir, 20 ins. diam., bears S.64*W., 29 lks. dist.


Marked $\frac{1}{4}$ S 20 B T.

Descend 93 ft. over NE. slope.

57.10 Creek, 3 lks. wide, course SE.

Ascend 215 ft. over broken S. slope.

80.00 Set an iron post, 3 ft. long, 2 ins. in diam., 16 ins. in the ground to bedrock, supported in a mound of stone, with a 3 ft. base, 1 ft. high, for the cor. of secs. 16, 17, 20, and 21, with brass cap marked,



from which

A madrone, 4 ins. diam., bears N.35*E., 41 lks. dist.

Marked T 26 .S R 1 E S 16 B T.

A fir, 9 ins. diam., bears S.30*E., 141 lks. dist.

Marked T 26 S R 1 E S 21 B T.

A madrone, 4 ins. diam., bears S.40*W., 41 lks. dist.

Marked T 26 S R 1 E S 20 B T.

A madrone, 4 ins. diam., bears N.60*W., 25 lks. dist.

Marked T 26 S R 1 E S 17 B T.

Land, mountainous.

Soil, rocky loam, third rate.

Timber, fir and madrone.

Undergrowth, vine maple and second growth timber.