

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 26 S., R. 1 E.

CHAINS	
	S.89*43'E., on a random line bet. secs. 16 and 21.
40.00	Set temp. $\frac{1}{2}$ sec. cor.
79.88	Intersect the N. and S. line, 30 lks. S. of the cor. of
	secs. 15, 16, 21 and 22.
	Thence,
	N.89*56'W., on a true line bet. secs. 16 and 21.
	Ascend 205 ft. over E. slope, through timber and brush.
16.50	Spur, slopes SE.
	Descend 75 ft. over SW. slope.
24.40	Draw, course S.20*E.
	Ascend 212 ft. over E. slope.
36.00	Spur, slopes SE.
	Descend 12 ft. over SW. slope.
39.94	Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in
	the ground, for the $\frac{1}{2}$ sec. cor., with brass cap marked,
	<div style="text-align: center;"> S16 $\frac{1}{2}$— S21 1928 </div>
	from which
	A fir, 24 ins. diam., bears N.63*E., 67 lks. dist.
	Marked $\frac{1}{4}$ S 16 B T.
	A fir, 20 ins. diam., bears S.55*E., 50 lks. dist.
	Marked $\frac{1}{4}$ S 21 B T.
48.60	Creek, 1 lk. wide, course SE.
	Ascend 390 ft. over broken E. slope.
73.40	Spring branch, 1 lk. wide, course SE.
78.00	Spur, slopes SE.
79.88	The cor. of secs. 16, 17, 20 and 21.
	Land, mountainous.
	Soil, rocky, loam, third rate.
	Timber, fir and madrone.
	Undergrowth, vine maple and second growth timber.