

Subdivisions, T. 26 S., R. 1 E.

CHAINS

S 9  
 $\frac{1}{4}$  —————  
 S 16  
 1928

from which

A cedar, 10 ins. diam., bears N.70\*E., 70 lks. dist.

Marked  $\frac{1}{4}$  S 9 B T.

A fir, 30 ins. diam., bears South, 42 lks. dist.

Marked  $\frac{1}{4}$  S 16 B T.

Ascend 50 ft. over SE. slope.

44.10 Spur, slopes N.

Descend 94 ft. over NW. slope.

46.60 Creek, 2 lks. wide, course N.

Ascend 415 ft. over broken NE. slope.

49.80 Point of small spur, slopes NE.

53.70 Spring branch, 1 lk. wide, course N.60\*E.

58.40 Small spur, slopes N.60\*E.

68.30 Creek, 2 lks. wide, course N.65\*E.

79.96 The cor. of secs. 8, 9, 16 and 17.

Land, mountainous.

Soil, rocky, third rate.

Timber, fir, cedar and pine.

Undergrowth, vine maple.

N.0\*03\*W., bet. secs. 8 and 9.

Descend 130 ft. over broken NE. slope, through timber and brush.

.70 Spring branch, 1 lk. wide, course N.70\*E.

7.20 Creek, 2 lks. wide, course NE.

10.10 Creek, 1 lk. wide, course E.

Ascend 35 ft. over SE. slope.

14.10 Spur, slopes NE.

Descend 170 ft. over broken NE. slope.

32.60 Draw, course N.80\*E.

Ascend 30 ft. over SE. slope.