

County Surveyor's Record, Douglas County, Oregon


Subdivisions, T. 26 S., R. 1 E.

CHAINS

38.00 Spur, slopes E.

Descend 32 ft. over NE. slope.

40.00 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap marked,



from which

A fir, 7 ins. diam., bears N.7*E., 82 lks. dist.

Marked $\frac{1}{4}$ S 9 B T.

A fir, 9 ins. diam., bears N.39*W., 124 lks. dist.

Marked $\frac{1}{4}$ S 8 B T.

Descend 50 ft. over NE. slope.

43.90 Creek, 1 lk. wide, course E.

Ascend 124 ft. over SE. slope.


55.70 Spur, slopes E.

Descend 214 ft. over broken NE. slope.

62.97 Panther Creek Way Trail, bears NE. and SW.

70.30 Creek, 2 lks. wide, course NE.

80.00 Set an iron post, 3 ft. long, 2 ins. in diam., 27 ins. in the ground, for the cor. of secs. 4, 5, 8, and 9, with brass cap marked,



from which

A cedar, 14 ins. diam., bears N.45*E., 37 lks. dist.

Marked T 26 S R 1 E S 4 B T.

A fir, 30 ins. diam., bears S.50*E., 147 lks. dist.

Marked T 26 S R 1 E S 9 B T.

A fir, 12 ins. diam., bears S.10*W., 52 lks. dist.

Marked T 26 S R 1 E S 8 B T.

A fir, 32 ins. diam., bears N.30*W., 54 lks. dist.

Marked T 26 S R 1 E S 5 B T.