


Subdivisions, T. 26 S., R. 1 E.

CHAINS



from which

A fir, 24 ins. diam., bears S.46*E., 33 lks. dist.

Marked $\frac{1}{4}$ S 29 B T.

A fir, 30 ins. diam., bears S.16*W., 37 lks. dist.

Marked $\frac{1}{4}$ S 30 B T.

Ascend 80 ft. over SE. slope.


49.00 Spur, slopes E.

Descend 100 ft. over broken NE. slope.

64.20 Creek, 1 lk. wide, course E.

Ascend 54 ft. over broken SE. slope.

80.00 Set an iron post, 3 ft. long, 2 ins. in diam., 27 ins. in the ground, for the cor. of secs. 19, 20, 29 and 30, with brass cap marked,



from which

A pine, 20 ins. diam., bears N.8*E., 45 lks. dist.

Marked T 26 S R 1 E S 20 B T.

A hemlock, 22 ins. diam., bears S.25*E., 97 lks. dist.

Marked T 26 S R 1 E S 29 B T.

A fir, 24 ins. diam., bears S.8*W., 77 lks. dist.

Marked T 26 S R 1 E S 30 B T.

A hemlock, 14 ins. diam., bears N.58*W., 100 lks.

Marked T 26 S R 1 E S 19 B T.

Land, mountainous.

Soil, rocky loam, third rate.

Timber, fir, hemlock, yew and chinquapin.

Undergrowth, vine maple and rhododendron.