

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 26 S., R. 1 E.

CHAINS

N.89*53'E., on a random line bet. secs. 20 and 29.

40.00 Set temp. 1/4 sec. cor.

79.86 Intersect the N. and S. line, 44 lks. N. of the cor. of
secs. 20, 21, 28 and 29.

Thence,

N.89*48'W., on a true line bet. secs. 20 and 29.

Descend 370 ft. over NW. slope, through timber and brush.

12.40 Creek, 1 lk. wide, course N.

Ascend 60 ft. over NE. slope.

14.30 Spur, slopes N.

Descend 60 ft. over NW. slope.

17.50 Draw, course N.

Ascend 250 ft. over broken NE. slope, changing to E.

25.40 Panther Creek, 5 lks. wide, course NE.

39.30 Creek, 1 lk. wide, course SE.

39.93 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in
the ground, for the 1/4 sec. cor., with brass cap marked,

S20
1/4
S29
1928

from which

A fir, 8 ins. diam., bears N.34*E., 19 lks. dist.

Marked 1/4 S 20 B T.

A fir, 12 ins. diam., bears S.5*W., 32 lks. dist.

Marked 1/4 S 29 B T.

Ascend 630 ft. over broken E. slope.

74.50 Creek, 2 lks. wide, course SE.

79.86 The cor. of secs. 19, 20, 29 and 30.

Land, mountainous.

Soil, rocky, third rate.

Timber, fir, cedar and hemlock.

Undergrowth, vine maple and second growth timber.