

8/22  
 County Surveyor's Record, Douglas County, Oregon

Retracement of Boundaries of H. E. S. No. 229

CHAINS	
37.97	<p>12x10x2 ins. above ground, marked and witnessed as described in the official record.</p> <p>S.60*30'E., retracing line 1-2, H. E. S. No. 229</p> <p>Cor. No. 2, H. E. S. No. 229, which is a stone, 8x8x6 ins. above ground, marked and witnessed as described in the official record, bears N.29*30'E. 11 lks. dist.</p> <p>True bearing and length of this line is S.60*40'E., 37.97 chs.</p> <p>Thence,</p> <p>S.14*51'E., retracing line 2-3.</p>
15.92	<p>Intersect cor. No. 3, H. E. S. No. 229, which is a stone, 12x10x10 ins. above ground, marked and witnessed as described in the official record.</p> <p>True bearing and length of this line is S.14*51'E., 15.92 chs.</p> <p>Thence</p> <p>S.65*W., retracing line 3-4;</p>
26.80	<p>Cor. No. 4, H. E. S. No.229, which is a fir, 40 ins. diam., marked and witnessed as described in the official record, bears N.25*W., 10 lks. dist.</p> <p>True bearing and length of this line is S.65*12'W., 26.80 chs.</p> <p>Thence</p> <p>S.28*41'E., retracing line 4-5</p>
10.92	<p>Intersect cor. No. 5, H. E. S. No. 229, which is a stone 8x10x12, ins. above ground, and marked and witnessed as described in the official record.</p> <p>True bearing and length of this line is S.28*41'E., 10.92 chs.</p> <p>Thence</p> <p>N.89*02'W., retracing line 5-6</p>
8.98	<p>Intersect cor. No. 6, H. E. S. No.229, which is a fir, 18 ins. diam., marked and witnessed as described in</p>