

County Surveyor's Record, Douglas County, Oregon

Retracement of Boundaries of H. E. S. No. 142.

CHAINS	
43.73	<p>is N.6*21'E., 47.34 chs.; of line 1-2, H. E. S. No. 227 is N.6*21'E., 42.78 chs.</p> <p>Thence S.57*06'W., retracing line 2-3, H. E. S. No. 142</p> <p>Cor. No. 3, H. E. S. No. 142, which is a stone, 10x6x8 ins. above ground, marked and witnessed as described in the official record, bears N.32*54'W., 9 lks. dist.</p> <p>True bearing and length of this line is S.57*13'W., 43.73 chs.</p>
35.61	<p>Thence S.15*40'E., retracing line 3-4.</p> <p>Cor. No. 4, H. E. S. No. 142, which is a stone, 14x8x10 ins. above ground, marked and witnessed as described in the official record, bears S.74*20'W., 55 lks. dist.</p> <p>True bearing and length of this line is S.14*47'E., 35.62 chs.</p>
10.86	<p>Thence N.89*43'E., retracing line 4-5.</p> <p>Cor. No. 5, H. E. S. No. 142, which is determined by original bearing trees; in middle of road.</p> <p>A fir, 16 ins. diam., bears N.71*E., 35 lks. dist., mkd. 5 H E S 142 B T</p> <p>A fir, 14 ins. diam., bears S.88*W., 25 lks. dist., mkd. 5 H E S 142 B T</p> <p>bears S.0*17'E., 10 lks. dist.</p> <p>True bearing and length of this line is S.89*44'E., 10.86 chs.</p>
15.96	<p>Thence N.47*40'E., retracing line 5-1</p> <p>Cor. No. 1, H. E. S. 142, place of beginning, bears N.42*20'W., 31 lks. dist.</p>