

County Surveyor's Record, Douglas County, Oregon

Retracement of Boundaries of H. E. S. No. 178

CHAINS	
	S.44*03'W., retracing line 1-2, H.E.S. No. 178
15.25	<p>Cor. No. 2, H. E. S., No. 178, which is a stone, 10x6x8 ins. above ground, marked and witnessed as described in the official record, bears S.45*57'E., 16 lks. dist.</p> <p>True bearing and length of this line is S.43*28'W., 15.25 chs.</p> <p>Thence</p>
	S.7*39'E., retracing line 2-3
9.89	<p>Cor. No. 3, H. E. S. No. 178, which is a stone, 7x8x8 ins. above ground, marked and witnessed as described in the official record, bears N.82*21'E., 12 lks. dist.</p> <p>True bearing and length of this line is S.8*21'E., 9.89 chs.</p> <p>Thence</p>
	N.74*34'W., retracing line 3-4
46.39	<p>Cor. No. 4, H. E. S. No. 178, which is a stone, 4x10x8 ins. above ground, marked and witnessed as described in the official record, bears S.15*26'W., 60 lks. dist.</p> <p>True bearing and length of this line is N.75*18'W., 46.40 chs.</p> <p>Thence</p>
	N.7*57'E., retracing line 4-5
11.80	<p>Cor. No. 5, H. E. S. No. 178, which is a stone, 15x10x12 ins. above ground, marked and witnessed as described in the official record, bears N.82*03'W., 16 lks. dist.</p> <p>True bearing and length of this line is N.7*09'E., 11.80 chs.</p> <p>Thence</p>