

County Surveyor's Record, Douglas County, Oregon

Retracement of Boundaries of H. E. S. No. 93

CHAINS	N.56*34'W., retracing line 2-3.
6.95	Cor. No. 3, H. E. S. No. 93, which is a cross (X) on S. end of boulder in place, 4x4x $\frac{1}{2}$ ft. above ground, marked and witnessed as described in the official record. True bearing and length of this line is N.56*34'W., 6.95 chs. Thence
15.14	N.87*40'W., retracing line 3-4. Cor. No. 4, H. E. S. No. 93, which is a stone, 6x6x10 ins. above ground, firmly set, marked and witnessed as described in the official record, bears S.2*20'W., 1ks. dist. True bearing and length of this line is N.87*56'W., 15.14 chs. Thence
21.82	N.9*45'W., retracing line 4-5. Intersect line bet. secs. 17 and 20.
24.26	Cor. No. 5, H. E. S. No. 93, which is a stone, 8x8x8 ins. above ground, firmly set, marked and witnessed as described in the official record, bears N.80*15'E., 30 lks. dist. True bearing and length of this line is N.9*02'W., 24.26 chs. Thence
19.87	S.88*44'E., retracing line 5-6. Cor. No. 6, H. E. S. No. 93, which is a stone, 8x12x10 ins. above ground, firmly set, marked and witnessed as described in the official record, bears N.1*16'E., 10 lks. dist. True bearing and length of this line is S.89*01'E., 19.87 chs. Thence