

6th Standard Parallel South, through R. 1 E.

CHAINS

- A fir, 36 ins. in dia., bears S.20*W. 53 lks. dist.,
marked S C $\frac{1}{4}$ S B T.
- 51.20 Spring branch 2 lks. wide course SE.
- 63.90 Nickel Creek 2 lks. wide course South.
- 68.00 Offset N.4chs.10 lks avoid rocky bluffs.
- 72.34 Came back to line again.
- 80.00 Set post 48x4 ins. firmly in the ground for stand. cor.
to secs. 32 and 33, marked S C T 27 S R 1 E on N S
33 on E and S 31 on W faces with 4 notches on E and
2 on W edges from which,
A fir, 18 ins. in dia., bears N.20*E. 33 lks. dist.,
marked T 27 S R 1 E S 33 B T.
A fir, 24 ins. in dia., bears N.23*W. 69 lks. dist.,
marked T 27 S R 1 E S 32 B T.
A fir, 18 ins. in dia., bears S.20*E. 43 lks. dist.,
marked S B T.
- Land 3rd rate.
Mountainous, rough and rocky.
Timber as usual good hemlock, spruce and pine.
Underbrush, thick fir and hemlock. June 27th 1883
-
- East on S. boundary of Sec. 33.
Var. 18*15'E.
- 14.50 Summit of ridge N. and S.
- 24.40 Stream 8 lks. wide course south.
- 40.00 Set post 44x4 ins. firmly in the ground for stand. $\frac{1}{4}$ sec.
cor. marked S C on N. and S. faces from which,
A fir, 24 ins. in dia., bears S. 14 lks. dist.,
marked S C $\frac{1}{4}$ S B T.
A fir, 30 ins. in dia., bears North 62 lks. dist.,
marked S C $\frac{1}{4}$ S B T.
- 45.15 Summit of ridge N and S.
- 66.85 Stream 4 lks. wide course south.
- 74.65 Stream 3 lks. wide course south