

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 27 S., R. 1 E.

CHAINS	Ascend 420 ft. over E. slope.
80.08	The cor. of secs. 2, 3, 10 and 11. Land, mountainous. Soil, rocky loam, 3rd rate. Timber, fir, pine, cedar and hemlock. Undergrowth, rhododendron, chinquapin and vine maple.
	N.0*02'W., on a random line bet. secs. 2 and 3.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.08	Intersect the N. bdy. of the Tp. 5 lks. E. of the cor. of secs. 2, 3, 34 and 35, hereinbefore described. Thence, S.0*04'E., on a true line bet. secs. 2 and 3. Along E. slope, through timber and brush.
12.00	Descend 568 ft. over broken S. slope.
30.10	Spring branch, 1 lk. wide, course SE.
33.00	Limpy Creek, 10 lks. wide, course NE.
38.10	Spring branch, 1 lk. wide, course NW.
40.08	Set an iron post, 3 ft. long, 1 in. in dia., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap marked
	$\begin{array}{c} \frac{1}{4} \\ \uparrow \\ \text{S } 3 \mid \text{S } 2 \\ \downarrow \\ 1927 \end{array}$
	from which, A cedar, 14 ins. in dia., bears S.66*E., 7 lks. dist., marked $\frac{1}{4}$ S 2 B T A pine, 24 ins. in dia., bears N.66*W., 44 lks. dist., marked $\frac{1}{4}$ S 3 B T
	Ascend 990 ft. over broken N. slope.
41.70	Spring branch, 1 lk. wide, course NE.
46.10	Same Spring branch, course NW.
80.08	The cor. of secs. 2, 3, 10 and 11. Land, mountainous. Soil, rocky loam, 3rd rate.