

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 27 S., R. 1 E.

CHAINS	<p>secs. 22, 23, 26 and 27.</p> <p>Thence,</p> <p>West, on a true line bet. secs. 22 and 27.</p> <p>Over mountainous land, through timber and brush.</p> <p>Descend 522 ft. over broken W. slope.</p> <p>19.00 Creek, 6 lks. wide, course NW.</p> <p>25.30 Little River, 10 lks. wide, course N.</p> <p>Ascend 382 ft. over broken E. slope.</p> <p>39.99 Set an iron post, 3 ft. long, 1 in. in dia., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap marked.</p> <div style="text-align: center; margin: 10px 0;"> $\frac{\frac{1}{4} S22}{S27}$ <p>1927</p> </div> <p>from which,</p> <p>A fir, 36 ins. in dia., bears S.22*E., 39 lks. dist., marked $\frac{1}{4}$ S 27 B T</p> <p>A cedar, 24 ins. in dia., bears N.26*W., 76 lks. dist., marked $\frac{1}{4}$ S 22 B T</p> <p>Ascend 65 ft. over E. slope.</p> <p>45.00 Spur, slopes NW.</p> <p>Descend 348 ft. over W. slope.</p> <p>62.20 Creek, 4 lks. wide, course NW.</p> <p>Ascend 165 ft. over E. slope.</p> <p>79.98 The cor. of secs. 21, 22, 27 and 28.</p> <p>Land, mountainous.</p> <p>Soil, rocky loam, 3rd rate.</p> <p>Timber, fir, cedar, pine and hemlock.</p> <p>Undergrowth, vine maple, rhododendron, chinquapin and second growth timber.</p>
--------	---

N.0*02'W., bet. secs. 21 and 22.

Over rolling land, through timber and brush.

Descend 212 ft. over gradual broken N. slope.