

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions, T. 27 S., R. 1 E.

## CHAINS

Descend 363 ft. over broken N. slope.

63.10 Hemlock Creek, 15 lks. wide, course NW.

Ascend 135 ft. over S. slope.

68.50 Spur, slopes NW.

Descend 164 ft. over broken N. slope.

76.00 Point of spur, slopes NW.

79.45 Set an iron post, 3 ft. long, 2 ins. in dia., 28 ins. in the ground, for the witness cor. of secs. 16, 17, 20 and 21, with brass cap marked.

W C	
T27SR1E	
S17	S16
S20	S21
1927	

from which,

A cedar, 8 ins. in dia., bears N.73°E., 36 lks. dist.,  
marked W C T 27 S R 1 E S 21 B T

A fir, 10 ins. in dia., bears S.34°E., 45 lks. dist.,  
marked W C T 27 S R 1 E S 21 B T

A fir, 14 ins. in dia., bears S.34°W., 53 lks. dist.,  
marked W C T 27 S R 1 E S 20 B T

A fir, 26 ins. in dia., bears N.30°W., 18 lks. dist.,  
marked W C T 27 S R 1 E S 20 B T

80.00 True point for cor. falls in the East fork of Hemlock Creek, 7 lks. wide, course W., where it is impracticable to establish sec. cor.

Land, mountainous.

Soil, rocky loam, 3rd rate.

Timber, fir, hemlock, pine and cedar.

Undergrowth, vine maple, rhododendron and second growth timber.

From the true point for the cor. of secs. 16, 17, 20 and 21.