

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 27 S., R. 1 E.

CHAINS	<p>Timber, hemlock, pine and fir. Undergrowth, vine maple, and rhododendron.</p>
40.00	<p>East, on a random line bet. secs. 29 and 32. Set temp. <math>\frac{1}{2}</math> sec. cor.</p>
79.88	<p>Intersect the N. and S. line, 28 lks. S. of the cor. of secs. 28, 29, 32 and 33.</p>
9.20	<p>Thence, S.89*48'W., on a true line bet. secs. 29 and 32. Over mountainous land, through timber and brush. Ascend 174 ft. over E. slope.</p>
39.94	<p>Ridge, bears N. and S. and Clover Creek Way Trail, bears N. and SE. Descend 370 ft. over broken W. slope. Set an iron post, 3 ft. long, 1 in. in dia., 27 ins. in the ground, for the <math>\frac{1}{2}</math> sec. cor., with brass cap marked.</p>
	<p style="text-align: center;"><math>\frac{1}{2} \frac{S29}{S32}</math> 1927</p>
45.00	<p>from which, A fir, 8 ins. in dia., bears N.25*E., 25 lks. dist., marked <math>\frac{1}{2}</math> S 29 B T A fir, 10 ins. in dia., bears S.10*W., 23 lks. dist., marked <math>\frac{1}{2}</math> S 32 B T Descend 30 ft. over W. slope.</p>
49.50	<p>Creek, 5 lks. wide, course NW. Ascend 71 ft. over NE. slope.</p>
63.60	<p>Spur, slopes NW. Descend 505 ft. over broken W. slope.</p>
66.10	<p>Creek, 8 lks. wide, course NW.</p>
67.10	<p>Spring branch, course N.</p>
79.88	<p>Creek, 2 lks. wide, course N.</p>
	<p>The cor. of secs. 29, 30, 31 and 32.</p>