

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 27 S., R. 1 E.

CHAINS

from which,

A hemlock, 16 ins. in dia., bears N.80*E., 29 lks. dist.,
marked T 27 S R 1 E S 30 C C B T

A hemlock, 10 ins. in dia., bears S.37*E., 52 lks. dist.,
marked T 27 S R 1 E S 31 C C B T

Land, mountainous.

Soil, rocky loam, 3rd rate.

Timber, fir, hemlock and pine.

Undergrowth, vine maple, rhododendron, chinquapin and
second growth timber.

From the cor. of secs. 29, 30, 31 and 32.

Thence,

N.0*04'W., bet. secs. 29 and 30.

Over mountainous land, through timber and brush.

Descend 569 ft. over broken NW. slope.


3.70 Spring branch, 2 lks. wide, course NW.

25.30 Creek, 6 lks. wide, course NW.

27.60 Creek, 5 lks. wide, course W.

Ascend 167 ft. over broken SW. slope.

40.00 Set an iron post, 3 ft. long, 1 in. in dia., 27 ins. in
the ground, for the 1/4 sec. cor., with brass cap marked.



from which,

A cedar, 14 ins. in dia., bears S.63*E., 73 lks. dist.,
marked 1/4 S 29 B T.

A fir, 16 ins. in dia., bears S.83*W., 50 lks. dist.,
marked 1/2 S 30 B T

40.60 Spur, slopes W.

Descend 261 ft. over NW. slope.

57.50 Creek, 5 lks. wide, course W.