

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 27 S., R. 1 E.

CHAINS

T27S	T27S	
S 1	S 6	— CC
	S 7	
R1W	R1E	
	1928	

from which,

A fir, 60 ins. in dia., bears N.10*E., 60 lks. dist.,
marked T 27 S R 1 E S.6 C C BT

A hemlock, 6 ins. in dia., bears S.75*E., 38 lks. dist.,
marked T 27 S R 1 E S.7 C C B T

Land, mountainous.

Soil, rocky loam, 3rd rate.

Timber, fir, hemlock, pine, yew, madrona and maple.

Undergrowth, vine maple, grease wood, rhododendron,
dogwood, chinquapin, salal, and second growth timber.

From the cor. of secs. 5, 6, 7 and 8, as hereinbefore
described.

Thence,

N.0*04*W., on a random line, bet. secs. 5 and 6.

40.00 Set temp. $\frac{1}{2}$ sec. cor.

80.49 Intersect the N. bdy. of the Tp. 25 lks. W. of the cor.
of secs. 5, 6, 31 and 32, hereinbefore described.

Thence,

S.0*07*W., on a true line bet. secs. 5 and 6.

Over mountainous land, through timber and brush.

Descend 524 ft. over broken SE. slope.

14.30 Draw, course S.15*E.

22.10 Spring branch, 1 lk. wide, course S.20*E.

31.50 Spring branch, 1 lk. wide, course SE.

35.10 Spring branch, 1 lk. wide, course S.15*E.

36.90 Spring branch, 1 lk. wide, course SE.

40.49 Set an iron post, 3 ft. long, 1 in. in dia., 27 ins.

in the ground, for the $\frac{1}{2}$ sec. cor., with brass cap marked.