

6th Standard Parallel South. T 27 S. R. 3 E.

CHAINS
40.00

Set post, 44x4 ins. firmly in the ground for stand. $\frac{1}{2}$ sec. cor. marked S C on N. and S. faces.

from which,

A fir, 16 ins. in dia., bears S.15*W., 55 lks. dist., marked S C $\frac{1}{2}$ S B T

A fir, 30 ins. in dia., bears N.25*E., 13 lks. dist., marked S C $\frac{1}{2}$ S B T

64.60

Stream 8 lks. wide, course NE.

80.00

Set post, 54x4 ins. firmly in the ground for stand. cor. to Tps. 27 S., Rs. 3 and 4 E. marked S C T 27 S on N. R 4 E S 31 on E. and R 3 E S 36 on W. faces.

from which,

A fir, 36 ins. in dia., bears N.44*E., 75 lks. dist., marked T 27 S R 4 E S 31 B T

A fir, 30 ins. in dia., bears N.25*W., 43 lks. dist., marked T 27 S R 3 E S 36 B T

A fir, 32 ins. in dia., bears S.60*E., 30 lks. dist., marked S B T

Land, 4th rate.

Heavily timbered with fir, hemlock and pine.

Thick underbrush, vine maple and fir.

Mountainous and rocky.

General Description.

Of the South boundary of T 27 S., R. 3 E. running east.

Land, 4th rate.

Mountainous, rocky and broken.

Timber, fir, spruce, hemlock and pine.

Underbrush same as Range 2.

Crossed Klamath Trail in sec. 33., and Black Rock ridge in sec. 34. Black Rock on the south of the line is quite a high and noted mountain and ridge.

The country on the north side of the line, as far as our observation extended, is rough and mountainous, heavily timbered, well watered, and the most noticeable feature is the extension North of the Black Rock ridge.