

County Surveyor's Record, Douglas County, Oregon

Township 27 South, Range 3 East.

Subdivision.

CHAINS	<p>marked T 27 S R 3 E S 26 B T</p> <p>Land, mountainous.</p> <p>Soil, sandy, gravelly, and rocky, 2nd and 3rd rate.</p> <p>Timber, fir, pine, and hemlock.</p> <p>Undergrowth, vine maple, alder, buck brush, small fir, pine, and hemlock.</p>
	<p>East, on random line, bet. secs. 25 and 36.</p>
40.00	<p>Set temp. $\frac{1}{4}$ sec. cor.</p>
79.82	<p>Intersect E. bdy. 2 lks. S. of the cor. of secs. 25, 30, 31 and 36.</p>
	<p>Thence, S.89*59'W., on a true line.</p>
	<p>Ascend 290 ft. over SE. slope to $\frac{1}{4}$ sec. cor., through medium timber and medium undergrowth.</p>
25.90	<p>Creek, 4 lks. wide, course SE. thence up the creek.</p>
38.75	<p>Leave the creek, which rises NW.</p>
39.91	<p>Set an iron post, 3 ft. long, 1 in. in dia., 30 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked.</p>
	$\begin{array}{r} \frac{1}{4} \text{ S } 25 \\ \text{S } 36 \\ 1929 \end{array}$
	<p>from which,</p>
	<p>A hemlock, 14 ins. in dia., bears N.46*E., 26 lks. dist., marked $\frac{1}{4}$ S 25 B T</p>
	<p>A fir, 42 ins. in dia., bears S.46*W., 18 lks. dist., marked $\frac{1}{4}$ S 36 B T</p>
	<p>Ascend 65 ft. over E. slope.</p>
42.20	<p>Spur, bears SE. descend 30 ft. over SW. slope.</p>
48.00	<p>Draw, drains SE., ascend 1020 ft. over E. slope to</p>
79.82	<p>The cor. of secs. 25, 26, 35 and 36.</p>
	<p>Land, mountainous.</p>
	<p>Soil, sandy, gravelly and rocky, 2nd to 4th rate.</p>