

County Surveyor's Record, Douglas County, Oregon

10977

Township 27 South, Range 3 East.

Subdivision.

CHAINS

79.70 Intersect E. bdy. of Tp. 21 lks. S. of the cor. of
secs. 1, 6, 7 and 12.

Thence,

N.89°58'W., on a true line.

Over rolling land, through heavy timber and dense
undergrowth.

39.74 A fir, 60 ins. in dia., on line. marked with 2 horizontal
grooves on E. and W. faces.

39.85 Set an iron post, 3 ft. long, 1 in. in dia., 27 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked.

$\frac{1}{4}$ S 1
S 12
1929

from which,

A fir, 34 ins. in dia., bears S.28°E., 21 lks. dist.,
marked $\frac{1}{4}$ S 12 B T

A fir, 14 ins. in dia., bears N.18°W., 120 lks. dist.,
marked $\frac{1}{4}$ S 1 B T

48.00 Leave heavy timber, bears NW. and S.

66.52 Road, bears NW. and SE.

75.00 Enter heavy timber, bears NE. and SW.

79.70 Cor. of secs. 1, 2, 11 and 12.

Land, rolling.

Soil, sandy and gravelly, 1st and 2nd rate.

Timber, fir, pine, and hemlock.

Undergrowth, thorn, mountain laurel, rhododendron,
small fir, pine, and hemlock.

N.0°01'W., on a random line, bet. secs. 1 and 2.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

82.89 Intersect N. bdy. of Tp. 28 lks. E. of the cor. of
secs. 1, 2, 35 and 36.

Thence,