

County Surveyor's Record, Douglas County, Oregon

Township 27 South, Range 3 East.

Subdivision.

CHAINS	
	<p>A fir, 24 ins. in dia., bears N.42*E., 70 lks. dist., marked $\frac{1}{4}$ S 27 B T</p> <p>A fir, 60 ins. in dia., bears S.71*E., 23 lks. dist., marked $\frac{1}{4}$ S 34 B T</p> <p>Descend 1100 ft. over broken NW. slope to</p>
80.36	<p>The cor. of secs 27, 28, 33 and 34.</p> <p>Land, mountainous.</p> <p>Soil, gravelly and rocky, 2nd to 4th rate.</p> <p>Timber, fir, pine and hemlock.</p> <p>Undergrowth, rhododendron, vine, maple, huckleberry, hazel, small fir, pine and hemlock.</p>
	<p>N.0*02'W., bet. secs. 27 and 28.</p> <p>Descend 185 ft. over N. slope, through heavy timber and dense undergrowth.</p>
5.10	<p>Creek, 7 lks. wide, from SW., thence in creek bed.</p>
19.65	<p>Leave the creek, course NE., ascend 35 ft. over SE. slope.</p>
21.50	<p>Spur, bears E., descend 60 ft. over NE. slope.</p>
30.50	<p>Creek, 3 lks. wide, course NE., ascend 35 ft. over SE. slope to</p>
40.00	<p>Set an iron post, 3 ft. long, 1 in. in dia., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked.</p> <div style="text-align: center;"> $\frac{1}{4}$ S 28 S 27 1929 </div> <p>from which,</p> <p>A fir, 20 ins. in dia., bears N.68*E., 17 lks. dist., marked $\frac{1}{4}$ S 27 B T</p> <p>A fir, 28 ins. in dia., bears N.36*W., 24 lks. dist., marked $\frac{1}{4}$ S 28 B T</p> <p>Thence over E. slope.</p>
45.00	<p>Descend 315 ft. over broken NE. slope to sec. cor.</p>