

## County Surveyor's Record, Douglas County, Oregon

Township 27 South, Range 3 East.  
Subdivision.

CHAINS

N.89°53'E., on a random line, bet. secs. 15 and 22.  
40.00 Set temp.  $\frac{1}{4}$  sec. cor.  
80.02 Intersect N. and S. line, 18 lks. N. of the cor. of  
secs. 14, 15, 22 and 23.  
Thence,  
N.89°59'W., on a true line.  
Descend 125 ft. over NW. slope, through heavy timber and  
dense undergrowth.  
11.76 Creek, 5 lks. wide, course NE., ascend 215 ft. over NE.  
slope to  
40.01 Set an iron post, 3 ft. long, 1 in. in dia., 28 ins. in  
the ground, for  $\frac{1}{4}$  sec. cor., with brass cap marked,  
$$\begin{array}{r} \frac{1}{4} \text{ S } 15 \\ \frac{1}{4} \text{ S } 22 \\ 1929 \end{array}$$
  
from which,  
A fir, 12 ins. in dia.; bears N.78°E., 40 lks. dist.,  
marked  $\frac{1}{4}$  S 15 B T  
A fir, 10 ins. in dia.; bears S.15 $\frac{1}{2}$ °E., 19 lks. dist.,  
marked  $\frac{1}{4}$  S 22 B T  
Ascend 180 ft. over NE. slope.  
55.75 Spur, bears NE., descend 185 ft. over NW. slope.  
67.11 Creek, 6 lks. wide, course N., ascend 200 ft. over SE.  
slope to sec. cor.  
78.69 Trail, bears NE. and SW.  
80.02 The cor. of secs. 15, 16, 21 and 22.  
Land, mountainous.  
Soil, sandy, gravelly, and rocky, 2nd rate.  
Timber, fir, pine, hemlock and cedar.  
Undergrowth, rhododendron, vine maple, hazel, willow,  
small fir, pine, and hemlock.

N.0°02'W., bet. secs. 15 and 16.