

## County Surveyor's Record, Douglas County, Oregon

Township 27 South, Range 3 East.

Subdivision.

CHAINS

Descend 130 ft. over N. slope.

48.20 Draw, drains NE. ascend 60 ft. over SE. slope.

53.20 Spur, bears NE., descend 50 ft. over N. slope.

65.10 Draw, drains, NE., ascend 70 ft. over SE. slope.

72.40 Spur, bears NE. descend 120 ft. over NW. slope to

80.00 Set an iron post, 3 ft. long, 2 ins. in dia., 24 ins. in the ground, for cor. of secs. 16, 17, 20 and 21, with brass cap marked.

T 27 S R 3 E
S 17   S 16
S 20   S 21
1929

from which,

A cedar, 42 ins. in dia., bears N.60\*E., 6 lks. dist.,  
marked T 27 S R 3 E S 16 B T

A fir, 24 ins. in dia., bears S.64\*E., 25 lks. dist.,  
marked T 27 S R 3 E S 21 B T

A hemlock, 14 ins. in dia., bears S.32\*W., 16 lks. dist.,  
marked T 27 S R 3 E S 20 B T

A fir, 20 ins. in dia., bears N.38\*W., 60 lks. dist.,  
marked T 27 S R 3 E S 17 B T

Land, mountainous.

Soil, sandy, gravelly, and rocky, 2nd and 3rd rate.

Timber, fir, pine, hemlock, and cedar.

Undergrowth, rhododendron, willow, hazel, vine maple,  
small fir, pine, and hemlock.

N.89\*48'E., on a random line, bet. secs. 16 and 21.

40.00 Set temp.  $\frac{1}{4}$  sec. cor.

80.10 Intersect N. and S. line, 9 lks. N. of the cor. of secs. 15, 16, 21 and 22.

Thence,

S.89\*52'W., on a true line.