

County Surveyor's Record, Douglas County, Oregon

Township 27 South, Range 3 East.

Subdivision.


CHAINS

slope.

19.00 Spur, bears NE., descend 250 ft. over N. slope.

38.00 Creek, 2 lks. wide, course NE., thence over E. slope to

40.00 Set an iron post, 3 ft. long, 1 in. in dia., 26 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked.



from which,

A fir, 22 ins. in dia., bears S.87*E., 76 lks. dist., marked $\frac{1}{4}$ S 9 B T

A fir, 10 ins. in dia., bears N.72*W., 32 lks. dist., marked $\frac{1}{4}$ S 8 B T


Ascend 110 ft. over SE. slope.

47.80 Spur, bears NE., descend 145 ft. over NE. slope.

56.43 Creek, 1 lk. wide, course E., ascend 175 ft. over SE. slope.

78.50 Spur, bears E., descend slightly over E. slope to

80.00 Set an iron post, 3 ft. long, 2 ins. in dia., 24 ins. in the ground, for cor. of secs. 4, 5, 8 and 9, with brass cap marked,



from which,

A fir, 15 ins. in dia., bears N.65 $\frac{1}{2}$ *E., 96 lks. dist., marked T 27 S R 3 E S 4 B T

A fir, 14 ins. in dia., bears S.72*E., 123 lks. dist., marked T 27 S R 3 E S 9 B T

A fir, 16 ins. in dia., bears S.42*W., 41 lks. dist., marked T 27 S R 3 E S 8 B T

A fir, 16 ins. in dia., bears N.43*W., 43 lks. dist., marked T 27 S R 3 E S 5 B T

Land, mountainous.