

County Surveyor's Record, Douglas County, Oregon

Township 27 South, Range 3 East.
Subdivision.

CHAINS

from which,
A pine, 10 ins. in dia., bears S.13 $\frac{1}{2}$ *W., 78 lks. dist.,
marked $\frac{1}{4}$ S 18 B T
A fir, 6 ins. in dia., bears N.71 $\frac{1}{2}$ *W., 35 lks. dist.,
marked $\frac{1}{4}$ S 7 B T

Ascend 410 ft. over broken SW. slope.
58.62 Creek, 2 lks. wide, course SW., ascend 500 ft. over
broken NW. slope to

79.81 The cor. of secs. 7, 8, 17, and 18.
Land, mountainous.
Soil, gravelly and rocky, 3rd and 4th rate.
Timber, fir, pine, and hemlock.
Undergrowth, rhododendron, chinquapin, small fir,
pine, and hemlock.


N.0*04*W., bet. secs. 7 and 8.
Descend 125 ft. over NW. slope, through scattering
timber and dense undergrowth.

6.28 Creek, 1 lk. wide, course SW., ascend 400 ft. over S.
slope.

24.00 Spur, bears NW., descend 200 ft. over N. slope to $\frac{1}{4}$ sec.
cor.

25.90 Trail, bears NW. and SE.

40.00 Set an iron post, 3 ft. long, 1 in. in dia., 28 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked.



from which,
A fir, 10 ins. in dia., bears S.78*E., 53 lks. dist.,
marked $\frac{1}{4}$ S 8 B T
A fir, 11 ins. in dia., bears S.62*W., 13 lks. dist.,