

6th Stan. Par. South of T. 27 South R. 6½ East.

CHAINS

on W. edges from which:

A fir, 20 ins. diam., bears N.40*E., 8 lks.

dist., marked T 27 S R 6½ E S 33 B T

A fir, 10 ins. diam., bears N.12*W., 20 lks.

dist., marked T 27 S R 6½ E S 32 B T

A fir, 18 ins. diam., bears S.80*E., 20 lks.

dist., marked S B T

Land, rough and mountainous- 4th rate, dense pine and fir timber.

Thick underbrush of pine, fir and manzanita.

West on South bdy. of Sec. 32.

Va. 18*E.

Ascending gradually thru pine bottom

40.00 Set post, 44 x 4 ins. firmly in the ground, for Stan ¼

Sec. cor., marked S. C. on N. and S. faces from which:

A spruce, 30 ins. diam., bears S.60*E., 16 lks.

dist., marked S C ¼ S B T

A fir, 10 ins. diam., bears N.50*W., 15 lks.

dist., marked S C ¼ S B T

Ascend up high steep ridge

All the posts on this line having been moved W. 11.60

chs., the distance from ¼ post on S. bdy. of sec. 32 to W. bdy. of R 6½ E will be 51.60 chs.

91.60 To cor. tps . 27 S Rs 6 & 6½ E.

July 17th, 1883

(See General description attached) - I.F.R.

Exterior lines of T. 27 S., R. 6½ E., W. M.,
As surveyed by Samuel C. Flint, U.S. Deputy Surveyor,
Under contract #484, dated July 28, 1883.

East Bdy. of T 27 S R 6½ E.

I began at closing standard cor. on W. bdy. of sec. 6 T 28 S R 7 E., and T 27 S R 6½ E S36 which is a post 4 ins. square firmly set in the ground, and marked C S C T 28 S R 7 E S 6 on East and C S C T 27 S R 6½ E. S36 on West faces, with 5 notches on W. and 6 on N. edges, from which: