

East Boundary of T. 27 S. R. 6 $\frac{1}{2}$ E.

CHAINS	
38.05	Stream, 8 lks. wide, course East.
40.00	Set post, 44 x 4 ins. sqr. 12 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S on W. face, from which: A pine, 6 ins. diam., bears S.80*E., 29 lks. dist., marked $\frac{1}{4}$ S B T A pine, 10 ins. diam., bears S.67*W., 30 lks. dist., marked $\frac{1}{4}$ S B T
42.50	Summit of Hill, course E. and W.
69.57	Cor. to W. bdy. of secs. 19 & 30 T 27 S R 7 E
80.00	Set post, 48 x 4 ins. sqr. 20 ins. in the ground, for cor. to secs. 13 and 24, marked T 27 S R 6 $\frac{1}{2}$ E S 24 on SW. and sec. 13 on NW. faces, with 3 notches on N. and S. edges, from which: A pine, 16 ins. diam., bears S.55*W., 44 lks. dist., marked T 27 S R 6 $\frac{1}{2}$ E S 24 B T. A pine, 12 ins., diam., bears N.55*W., 15 lks. dist., marked T 27 S R 6 $\frac{1}{2}$ E S 13 B T. A pine, 14 ins. diam., bears N.70*E., 12 lks. dist., marked T 27 S R 7 E S 19 B T.
	Land, hilly and broken. Densely covered with forests of pine, and fir timber. Little underbrush- soil 3rd. rate. <div style="text-align: right;">August 11th, 1883.</div>
	North on E. bdy. of Sec. 13. Va. 18*E.
0.30	Stream, 2 lks. wide, course East. Ascend hill.
10.50	Summit of hill, course E. and W.
12.00	Descend hill.
21.00	Stream, 15 lks. wide, course SE.
40.00	Set post, 44 x 4 ins. sqr. 12 ins. in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on W. face, from which: