

## County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 27 S. R. 6 $\frac{1}{2}$  E.

## CHAINS

A pine, 6 ins. diam., bears N.16\*W., 20 lks.  
dist., marked  $\frac{1}{4}$  S B T

A pine, 6 ins. diam., bears S.45\*W., 3 lks.  
dist., marked  $\frac{1}{4}$  S B T

49.65 Stream, 5 lks. wide, course NE.

57.00 Stream, 5 lks. wide, course SE.

60.65 Stream, 5 lks. wide, course NE.

61.50 Stream, 5 lks. wide, course SE.

70.15 Stream, 5 lks. wide, course NE.

78.15 Stream, 5 lks. wide, course SE.

79.80 Corner to secs. 25, 26, 35 and 36.

Land mountainous and soil 3rd. rate.

Dense forests of pine, fir and hemlock timber.

Undergrowth pine and fir.

Aug 24, 1883.

North bet. secs. 25 and 26.

Va. 18\* E.

Ascending hill

19.50 Summit of hill

40.00 Set post, 44 ins. by 4 ins. sq. 15 ins. in the ground,  
for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  S on W. face, from which:

A pine, 10 ins diam., bears N.53\*E., 28 lks.  
dist., marked  $\frac{1}{4}$  S B T

A pine, 7 ins. diam., bears S.75\*W., 19 lks.  
dist., marked  $\frac{1}{4}$  S B T

Descending from  $\frac{1}{4}$  S. cor.

80.00 Set pine post, 50 ins. by 4 ins. sq. 24 ins. in the  
ground, for cor. to secs. 23, 24 and 25 and 26,  
marked T 27 S S 24 on NE.- R 6 $\frac{1}{2}$  E S 25 on SE.  
S 26 on SW. and S 23 on NW. faces with 1 notch on E.  
and 2 on S. edges, from which:

A pine, 14 ins. diam., bears N.64\*E., 27 lks.  
dist., marked T 27 S R 6 $\frac{1}{2}$  E S 24 B T

A pine, 14 ins. diam., bears S.85\*E., 9 lks.  
dist., marked T 27 S R 6 $\frac{1}{2}$  E S 25 B T

A pine, 10 ins. diam., bears S.65\*W., 50 lks.