

Subdivisions of T. 27 S. R. 6 $\frac{1}{2}$  E.

CHAINS

A pine, 7 ins. diam., bears S.20\*W., 3 lks.

dist., marked S 14 M C B T

Land, hilly, covered with a dense forests of pine timber.

Underbrush pine.

Soil 3rd. rate.

West, on true line between sec. 12 and 13. Va. 18\*30'E.

From the cor. to secs. 12, 13 and 18, which is a post,

4 ins. sq., marked T 27 S R 6 $\frac{1}{2}$  E S 13 on SW. S 12

on NW. and R 7'E S 18 on SE. faces, with 4 notches

on S and 2 on N. edges, from which:

A pine, 12 ins. diam., bears S.52\*W., 39 lks.

dist., marked T 27 S R 6 $\frac{1}{2}$  E S 13 B T

A pine, 8 ins. diam., bears N.50\*W., 17 lks.

dist., marked T 27 S R 6 $\frac{1}{2}$  E S 12 B T

A pine, 6 ins. diam., bears S.72\*E., 16 lks.

dist., marked T 27 S R 7 E S 18 B T

Descend hill towards Lake

29.90

Intersect Fish Lake

Set post, 48 by 4 ins. sq. 18 ins. in the ground, for

Meander cor., bet. fract. of secs. 12 and 13, marked

on NE. face T 27 S S 12 M C and on SE. face R 6 $\frac{1}{2}$  E S

13 W M C on W. face, from which:

A pine, 10 ins. diam., bears N.57\*E., 18 lks.

dist., marked T 27 S R 6 $\frac{1}{2}$  E S 12 M C B T

A pine, 10 ins. diam., bears S.34\*E., 18 lks.

dist., marked T 27 S R 6 $\frac{1}{2}$  E S 13 M C B T

Land sloping toward Lake.

Covered with dense forests of pine timber and thick

brush of pine.

Soil 3rd. rate.

Sept. 4, 1883.