

## Sixth Standard Parallel South, through S. 5 E.

CHAINS

Ascend ridge.

80.00 Set post, 50x4 ins. firmly in the ground, for stan. cor. to secs. 32 and 33, mkd. S C T 27 S R 5 E on N, S 33 on E, and S 32 on W, faces, with 4 notches on E, and 2 on W. edges, from which

A fir, 10 ins. diam., bears N.30\*E., 10 lks. dist., mkd. T 27 S R 5 E S 33 B T.

A fir, 20 ins. diam., bears N.55\*W., 35 lks. dist., mkd. T 27 S R 5 E S 32 B T.

A fir, 24 ins. diam., bears S.15\*W., 11 lks. dist., mkd. S B T.

Land, 4th rate, mountainous, rough and rocky.

Timber, fir, hemlock and pine.

Pumice stone soil.

Thick underbrush of vine maple, cinnamon and mountain laurel.

July 9, 1883.

Va. 18\*30'E.

East, on S. bdy. of sec. 33.

Ascending rocky ridge.

40.00 Set post, 44x4 ins. firmly in the ground, for stan. cor. to 1/4 sec. mkd. S C on N. and S. faces, from which

A pine, 12 ins. diam., bears N.80\*W., 53 lks. dist., mkd. S C 1/4 S B T.

A pine, 10 ins. diam., bears S.45\*W., 39 lks. dist., mkd. S C 1/4 S B T.

Ascending.

80.00 Set post, 48x4 ins. firmly in the ground, for stan. cor. to secs. 33 and 34, mkd. S C T 27 S R 5 E on N, S 34 on E, and S 33 on W, faces, with 3 notches on E. and W. edges, from which