

Sixth Standard Parallel South, through R. 5 E.

CHAINS

Land, 4th rate, mountainous and rocky.

Timber, fir, pine, hemlock and spruce.

Thick underbrush of pine, fir and laurel.

Va. 15*E.

East, on S. bdy. of sec. 35.

Desc. mountain (in snow drifts).

40.00 Set post, 44x4 ins. firmly in the ground, for stan. 1/4 sec.

cor. mkd. S C on N. and S. faces, from which

A fir, 12 ins. diam., bears S.60*W., 35 lks. dist.,

mkd. S C 1/4 S B T.

A fir, 24 ins. diam., bears N.40*E., 17 lks. dist.,

mkd. S C 1/4 S B T.

Still descending mountain.

80.00 Set post, 50x4 ins. firmly in the ground, for stan. cor.

to secs. 35 and 36, mkd. S C T 27 S R 5 E on N, S 36

on E, and S 35 on W, faces, with 1 notch on E. and

5 on W. edges, from which

A Fir, 18 ins. diam., bears N. 58* E., 50 lks.

dist., marked T 27 S R 5 E S 36 B T.

A Fir, 12 ins. diam., bears N.53* W., 30 lks.

dist., marked T 27 S R 5 E S 35 B T.

A Fir, 24 ins. diam., bears S. 38* E., 24 lks.

dist., marked S B T.

Land, fourth rate.

Mountains, high and rocky.

Timber, Fir, Hemlock, Pine and Spruce.

Thick underbrush of manzanita, Fir and Pine.

July 10, 1883.