

Sixth Standard Parallel South, through R. 4 E.,
 As surveyed by, Samuel C. Flint, U. S. Deputy Surveyor,
 Under contract No. 473, dated June 5, 1883.

CHAINS	
	East, on S. bdy. of sec. 31. <div style="text-align: right;">Va.17*45'E.</div> Descend mountain.
39.00	Enter timbered bottom.
40.00	Set post, 44x4 ins. firmly in the ground, for standard 1/4 sec. cor. mkd. S C on N. and S. faces, from which A fir, 18 ins. diam., bears N.5*E., 19 lks. dist., mkd. S C 1/4 S B T. A fir, 8 ins. diam., bears S.15*W., 12 lks. dist., mkd. S C 1/4 S B T.
46.00	Clear creek, 75 lks. wide, course North.
47.40	Ascend, mountain.
70.00	Enter timbered bench.
80.00	Set post, 48x4 ins. firmly in the ground, for standard cor. of secs. 31 and 32, mkd. S C T 27 S R 4 E on N, S 32 on E, and 31 on W. faces, with 5 notches on E, and 1 notch on W. edges, from which A pine, 18 ins. diam., bears N.42*E., 14 lks. dist., mkd. T 27 S R 4 E S 32 B T. A fir, 10 ins. diam., bears N.25*W., 27 lks. dist., mkd. T 27 S R 4 E S 31 B T. A fir, 20 ins. diam., bears S.7*W., 15 lks. dist., mkd. S B T.
	Land, 3rd rate, heavily timbered with hemlock, fir, spruce and pine. Underbrush, thick with vine maple and fir.
	East, on S. bdy. of sec. 32. <div style="text-align: right;">Va.19'E.</div> Through heavily timbered flat.
40.00	Set post, 46x4 ins. firmly in the ground, for stan. 1/4 sec. cor. mkd. S C on N. and S. faces, from which A fir, 16 ins. diam., bears S.40*E., 10 lks. dist., mkd. S C 1/4 S B T.