

# County Surveyor's Record, Douglas County, Oregon

10241

6th Standard Parallel South, through Range 1 East,  
as Surveyed by Samuel C. Flint, Deputy Surveyor,  
under Contract No. 473, dated June 5, 1883.

CHAINS

From the standard cor. to Tps. 27 S., Rs. 1 W and 1 E., which is a post, 48x4 ins., firmly set in the ground, marked S C T 27 S on N, R 1 E S 31 on E and R 1 W S 36 on W faces, 6 notches on N, E, and W, from which

A Laurel, 8 ins. diam., bears N.25\*E., 26 lks.  
dist. marked T 27 S R 1 E S 31 B T.

A Fir, 24 ins. diam., bears N.50\*W., 194 lks.  
dist. marked T 27 S R 1 W S 36 B T.

A Laurel, 10 ins. diam., bears S.35\*W., 25 lks.  
dist. marked S B T.

June 26th, 1883.

East, on South Boundary of Sec. 31.

Var.18\*30'E.

- 39.00 Summit of mountain.
- 40.00 Set post, 44x4 ins. firmly in the ground for standard  $\frac{1}{4}$  sec. cor. marked S C on N and S faces, from which
  - A Fir, 18 ins. diam., bears N.10\*E., 35 lks.  
dist. marked S C  $\frac{1}{4}$  S B T.
  - A Fir, 18 ins. diam., bears S.2\*W., 21 lks.  
dist. marked S C  $\frac{1}{4}$  S B T.
- 65.00 Spring branch, 3 lks. wide, course North.
- 65.80 Spring branch, 3 lks. wide, course North.
- 68.12 Spring branch, 2 lks. wide, course North.
- 80.00 Set post, 48x4 ins. firmly in the ground for standard cor. to secs. 31 and 32 marked S C T 27 S R 1 E on N, S 32 <sup>on</sup> E and S 31 on W faces, with 5 notches on E and 1 on W edges, from which
  - A Fir, 8 ins. diam., bears N.25\*E., 26 lks.  
dist. marked T 27 S R 1 E S 32 B T.
  - A Fir, 9 ins. diam., bears N.15\*W., 37 lks.