

6th Standard Parallel South of Tp. 27 S., R 1 E.

CHAINS

Underbrush, Thick Fir and Hemlock.

June 27th, 1883.

East, on South Boundary of Sec. 33

Var. 18°15'E.

14.50 Summit of Ridge N and S

24.40 Stream, 8 lks. wide, course South.

40.00 Set post, 44x4 ins. firmly in the ground for standard  $\frac{1}{4}$

sec. cor. marked S C on N and S faces, from which

A Fir, 24 ins. diam., bears South 14 lks.

dist. marked S C  $\frac{1}{4}$  S B T.

A Fir, 30 ins. diam., bears North 62 lks.

dist. marked S C  $\frac{1}{4}$  S B T.

45.15 Summit of Ridge, N and S

66.85 Stream, 4 lks. wide, course South.

74.65 Stream, 3 lks. wide, course South.

80.00 Set post, 48x4 ins. firmly in the ground for Standard

cor. to secs. 33 and 34 marked S C T 27 S R 1 E on N,

S 34 on E and S 33 on W faces, with 3 notches on E

and W edges, from which

A Pine, 36 ins. diam., bears N.40°E., 18 lks.

dist. marked T 27 S R 1 E S 34 B T.

A Pine, 48 ins. diam., bears N.30°W., 27 lks.

dist. marked T 27 S R 1 E S 33 B T.

A Pine, 30 ins. diam., bears S.1°E., 25 lks.

dist. marked S B T.

Land, 3rd rate, rocky and mountainous.

Timber, Fir, Hemlock and Spruce.

Thick underbrush, of mountain Laurel, Vine Maple, and etc.