

6th Standard Parallel South of Tp. 27 S., R 1 E.

CHAINS

Peak, of Quartz Mountain S.25*E., say 20 chs. dist.

72.70 Stream, 25 lks. wide, course SE

79.00 Stream, 4 lks. wide, course South

80.00 Set post, 48x4 ins. firmly in the ground for standard cor. to secs. 35 and 36 marked S C T 27 S R 1 E on N, S 36 on E and S 35 on W faces, with 1 notch, on E and 5 on W edges, from which;

A Pine, 30 ins. diam., bears N.40*E., 27 lks. dist. marked T 27 S R 1 E S 36 B T.

A Chinquapin, 8 ins. diam., bears N.50*W., 31 lks. dist. marked T 27 S R 1 E S 35 B T.

A Pine, 24 ins. diam., bears S.35*W., 33 lks. dist. marked S B T.

Land, 4th rate.

Timber, Fir, Hemlock, Spruce and Pine.

Thick Underbrush, Fir, Mountain Laurel, and Vine Maple.

Mountainous rough and rocky

East, on South Boundary of sec. 36

Var.18*30'E.

38.48 Stream, 20 lks. wide, course South Ascend mountain ridge.

40.00 Set post, 44x4 ins. firmly in the ground for standard $\frac{1}{4}$ sec. cor. marked S C on N and S faces, from which

A Fir, 20 ins. diam., bears N.70*W., 28 lks. dist. marked S C $\frac{1}{4}$ S B T.

A Fir, 8 ins. diam., bears S.50*E., 182 lks. dist. marked S C $\frac{1}{4}$ S B T.

80.00 Set post, 48x4 ins. firmly in the ground for standard cor. to Tps. 27 S R 1 and 2 E marked S C T 27 S on N, R 2 E S 31 on E and R 1 E S 36 on W faces, with 6 notches on NE and W edges, from which

A Fir, 30 ins. diam., bears N.70*E., 28 lks.