

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 1 E., Resurvey of the Sixth Standard Parallel South through R. 1 E., and Resurvey of the Willamette Meridian through T. 28 S., as surveyed by Lincoln E. Wilkes, U. S. Cadastral Engineer, Otto L. Draper, U. S. Transitman, Norman D. Price, U. S. Transitman, under Special Instructions, dated December 21, 1920.

CHAINS

Resurvey of the Sixth Standard Parallel South through R. 1 E.

Having determined by retracement that this line is out of limits in both alinement and measurement, I proceed with an independent resurvey of same.

The standard Cor. of Tps. 27 S., Rs. 1 E. and 1 W. is a badly decayed fir post, 4 ins. square, 18 ins. above ground, loosely set, markings almost obliterated; from which

A laurel stump, 8 ins. diam., bears N. 25* E.,
26 lks. dist., no markings distinguishable.

A laurel stump, 10 ins. diam., bears S. 35* W.,
25 lks. dist., no markings distinguishable.

Find no evidence of bearing tree described as a
Fir, 24 ins. diam., bears N. 50* W., 194 lks.
dist., mkd. T27S R1W S36 BT.

Two bark scribed bearing trees not described in the original field notes were found as follows:

A fir, 7 ins. diam., bears N. 40* E., 30 lks.
dist., mkd. T27S R1E S31 BT.

A fir, 26 ins. diam., bears N. 40* W., 22 lks. dist.,
mkd. T27S R1W S36 BT.

In place of badly decayed post,

Set an iron post, 3 ft. long, 3 ins. diam., 27 ins. in the ground, for standard Cor. of Tps. 27 S., Rs. 1 E. and 1 W., with brass cap mkd.

SC
T27S
R1W R1E
S36 S31
1927

I blaze and mark new bearing trees as follows:

A fir, 7 ins. diam., bears N. 40* E., 30 lks.
dist., mkd. T27S R1E S31 SC BT.

A fir, 26 ins. diam., bears N. 40* W., 22 lks.
dist., mkd. T27S R1W S36 SC BT.