

County Surveyor's Record, Douglas County, Oregon

Resurvey of the Sixth Standard Parallel South through R. 1 E.

CHAINS

40.00 200 ft. below divide.

Set and iron post, 3 ft. long, 1 in. diam., 6 ins. in the ground, to bed rock, in a mound of stone, 5 ft. base, 2 ft. high, for standard $\frac{1}{4}$ sec. cor., with brass cap mkd.

SC
 $\frac{1}{4}$ S32

1927

from which

A fir, 30 ins. diam., bears N. 37* E., 101 lks. dist., mkd. $\frac{1}{4}$ S32 SC BT.

A fir, 14 ins. diam., bears N. 61* W., 49 lks. dist., mkd. $\frac{1}{4}$ S32 SC BT.

Desc. broken SE. slope over cliffs and slide rock.

46.00 Ravine, course SE.

54.45 Ravine, course SE.

61.15 Ravine, course SW.; 340 ft. below the standard $\frac{1}{4}$ sec. cor.; asc. 365 ft. over broken W. slope over cliffs and slide rock.

68.20 Spur, slopes SE. from N.; desc. broken SE. slope over cliffs and slide rock.

76.55 The old cor. established for standard cor. of secs. 32 and 33, bears S. 24 $\frac{3}{4}$ * W., 148 lks. dist.
I destroy all evidence of this cor.

80.00 260 ft. below spur.

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for standard cor. of secs. 32 and 33, with brass cap mkd.

S C
T27S | R1E
S32 | S33

T28S R1E
1927

from which

A cedar, 14 ins. diam., bears N. 58* E., 65 lks. dist., mkd. T27S R1E S33 SC BT.